

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

RECEIVED

AUG 1 5 2005

August 3, 2005

Air Protection Division (3AP12)

Dr. Roger C. Westman Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

Assistant Council Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745 ATTN: Steve Hepler

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 191003-2029 ATTN: James W. Hagedorn

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 05-0156

ACHD Reference Number: 6608 #19 Battery Igniter Flare

USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the outage. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

Anton Lukac Plant Manager Clairton Works

NOTICE OF BREAKDOWN OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 05-0156 ACHD Reference Number: 6608

2. Date & Time of Breakdown: Date: 08/02/05 Time: 0808 hours

3. Company Name: U.S. Steel Corporation - USS Clairton Works

4. Specific Equipment Involved or Affected: #19 Battery Igniter
Flare

5. BAPC Permit Number (if applicable):

6. Location: Clairton, PA

7. Nature and cause of breakdown: Tar removal maintenance was being performed on #19 Battery suction main when the flare tripped. The auto mercoid switch malfunctioned and allowed the igniter flare to remain open.

		Start	End	Duration		Flared	
Date	Battery	Time	Time	Min.	Sec.	Yes	No
08/02/05	19	08:08	08:21	13	00	Yes	

- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 Released products of combustion of Coke Oven Gas.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). Eye, Nose and Throat Irritant.

C. Amount of each type emitted (or likely to be emitted) .

Chemical	Quantity Released (lbs)
	427
NOx	78
SO ₂	2168
VOC	59

9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

The flare was manually closed and flaring was terminated at 0821 hours. The mercoid switch replacement was completed at 1100 hours and the automatic system was available for service.

10. Facility back in operation - Date: 08/02/05 Time: 1100 hours

Signature (clean /n. Apris Date 8/8/05

Senior Environmental Control Engineer Phone: 233-1015